

possibly tripping the veteran. This situation is exacerbated by poor illumination. [see also B3 below]			
RECOMMENDATIONS BELOW MAY REQUIRE VA SPECIAL HOUSING MODIFICATION GRANT OR LOAN (e.g., HISA)			
B1. Veteran is at risk of falling on the uneven graveled area adjacent to her front door patio area when entering and exiting her home. (see Exhibit 1c).	To increase the veteran's safety when entering and exiting her home	<p>(a) Level and pave area in front of the veteran's home. Area should be large enough to accommodate a vehicle and wide enough to allow the veteran a pathway to the car, allowing her to open the car door and get in and out of a vehicle while remaining on the paved area. This paved area should be on the same plane as the existing patio, meaning, stepless.</p> <p>(b) Install handrail on the paved area along the side that the veteran will use for getting in and out of vehicles.</p>	Veteran will experience increased sense of safety and confidence in her stability when using the front door of her home.
B2. Veteran is at risk of falling when entering and exiting the bathroom tub/shower to bathe or shower (see Exhibit 6c.)	To increase the veteran's safety when entering and exiting her tub/shower area.	<p>(a) <u>For showering:</u> Install one fixed grab bar EACH on the left and right and middle walls of the tub shower area per the veteran's height preference.</p> <p>(b) <u>For bathing:</u> Install fixed L-shaped grab bar to the middle wall, reachable from a seated position while taking a bath.</p>	Veteran will experience increased sense of safety and confidence in her stability when using entering and exiting her shower stall.
B3. Veteran is at risk of falling due to an abundance of things (in	To enable the veteran to move safely through her	Install additional and efficient storage systems within the home's	Veteran will experience increased sense of safety and confidence in her